

1 2






IN THE BOX









Torx driver T-7

Attachment Screws (Only two screws are required)

Ledge two parts

1 2






IN THE BOX







Torx driver T-7

Attachment Screws (Only two screws are required)

Ledge two parts